



## New Machinery Hazard Identification, Assessment & Risk Control Summary Sheet.

**Plant/Equipment Description:** *Future 150 Supreme Matboard Cutter.*

**Issue Date:** 9 / 12 / 04

**Revised Date:** N / A

<b>Hazard Type</b>	<b>Risk Score</b>	<b>Risk Control</b>
Entanglement	Low Risk	No loose clothing, jewellery to be worn. Ongoing operator training.
Crushing Fingers/hand during operation and maintenance.	Low Risk	Ongoing training.
Cutting, Stabbing & Puncturing Fingers with blade. Fingers/hand during maintenance. Eyes/face while cutting matboard.	Low Risk	Isolate power to machine prior to any checks or maintenance is carried out. Ongoing training and follow correct Safe Operating Procedure (SOP). Wear safety glasses.
Ergonomic Bending while cutting.	Low Risk	Ongoing training. Rotate operators as necessary.

**Note:** New Machinery Hazard / Control Summary Sheet to be read in conjunction  
with Future 150 Supreme Matboard Cutter Handbook.

***All operators must be familiar with the handbook and properly trained prior to use of the machine.***

Risk Assessment Conducted by:

Peter Shambre  
Peter Shambre & Assoc.  
Occupational Health & Safety  
Risk Management Consultants  
GRAD. DIP. ERG. MESA. AIIE  
9<sup>th</sup> December 2004

Joanne Vitiello  
Occupational Health & Safety Officer  
Antons Mouldings Pty Ltd.  
9<sup>th</sup> December 2004