



## New Machinery Hazard Identification, Assessment & Risk Control Summary Sheet.

**Plant/Equipment Description:** *Morso F Guillotine.*

**Issue Date:** 11 / 12 / 04

**Revised Date:** N / A

Hazard Type	Risk Score	Risk Control
Crushing Fingers/hand during operation and maintenance.	Low Risk	Ongoing training. Guards must be fitted at all times when operating machine.
Shearing Fingers/hand during operation and maintenance.	Low Risk	Ongoing training. Guards must be fitted at all times when operating machine.
Cutting, Stabbing and Puncturing Fingers/hand during operation and maintenance.	Low Risk	Ongoing training. Guards must be fitted at all times when operating machine.
Ergonomic Repetitive foot motion.	Low Risk	Ongoing training. Job rotate, and alternate between Right and Left foot when operating foot-pedal for extended periods.

**Note:** New Machinery Hazard / Control Summary Sheet to be read in conjunction with Morso F Guillotine Handbook.

*All operators must be familiar with the handbook and properly trained prior to use of the machine.*

Risk Assessment Conducted by:

Peter Shambre  
Peter Shambre & Assoc.  
Occupational Health & Safety  
Risk Management Consultants  
GRAD. DIP. ERG. MESA. AIIE  
11<sup>th</sup> December 2004

Joanne Vitiello  
Occupational Health & Safety Officer  
Antons Mouldings Pty Ltd.  
11<sup>th</sup> December 2004